IMG_1928.JPG
Site. Looking South.
11/30/2009

IMG_1932.JPG
Southeast corner of site. Looking East.
11/30/2009

IMG_1939.JPG
Trucks in the queue. Looking South.
11/30/2009

IMG_1955.JPG
Site. Looking West.
12/1/2009

IMG_1964.JPG
SPWI mechanics working on the D8R dozer.
12/1/2009

IMG_1968.JPG
Southeast corner of the site. 83 loads exported.
12/1/2009

IMG_1978.JPG
Trucks in the queue. 150 loads exported.
12/2/2009

IMG_1980.JPG

12/2/2009

IMG_1995.JPG
Loading trucks. 170 loads exported.
12/3/2009

IMG_1999.JPG
Site. Looking North.
12/3/2009

IMG_2002.JPG
Cut face near Southeast corner. Soil nail starting point.
12/3/2009

IMG_2006.JPG
SPWI loading trucks. Looking South.
12/4/2009

IMG_2013.JPG
SPWI loading trucks. Looking North.
12/4/2009

IMG_2016.JPG
Stuart Engineering laying out top of wall.
12/4/2009

IMG_2018.JPG
Drill rig mobilized.
12/4/2009

IMG_2020.JPG
Drill rig mobilized.
12/4/2009