6/21/2010
Grading/excavation south slopes.
IMG_1921.JPG

6/21/2010
Grading/excavation south slopes.
IMG_1925.JPG

6/22/2010
Grading/excavation near south slopes.
IMG_1935.JPG

6/25/2010
Constuction entrance.
IMG_1964.JPG

6/25/2010
Export operation.
IMG_1967.JPG

6/25/2010
Site. Looking west.
IMG_1970.JPG

6/25/2010
Site. Looking south.
IMG_1972.JPG

6/25/2010
Mockup wall panel forms.
IMG_1975.JPG