Site. Looking North.
12/22/2010
IMG_5879.JPG

Tech tank area filled with storm water.
12/22/2010
IMG_5880.JPG

Site. Looking North.
12/22/2010
IMG_5881.JPG

Tech tank area filled with storm water.
12/22/2010
IMG_5882.JPG

Stair #1 filled with storm water.
12/22/2010
IMG_5886.JPG

BMP's installed along Biological Grade.
12/22/2010
IMG_5889.JPG

GST removing sediment near the Keck lot entrance.
12/23/2010
IMG_5890.JPG

Forming L1 W2 line exterior wall.
12/23/2010
IMG_5895.JPG

Dewatering tech tank area.
12/23/2010
IMG_5896.JPG

Forming L1 deck pour area #4. Corridor 127 / Elevator 2.
12/23/2010
IMG_5897.JPG

Stripping L1 V1 line architectural exterior wall.
12/23/2010
IMG_5901.JPG