IMG_0080.JPG
East looking West

IMG_0082.JPG
Southeast looking Northwest

IMG_0077.JPG
East side

IMG_0074.JPG
North side

IMG_0073.JPG
Northwest corner

IMG_0071.JPG
Southwest corner

IMG_0070.JPG
South side

IMG_0111.JPG
Plaza level West - Southend

IMG_0112.JPG
Plaza West

IMG_0113.JPG
Plaza Norh

IMG_0114.JPG
Plaza East

IMG_0116.JPG
Plaza East- Southend

IMG_0110.JPG
Level 3 Plaza South

IMG_0121.JPG
Level 4 North Courtyard

IMG_0107.JPG
North Courtyard

IMG_0083.JPG
Lunch area ready for scratch & brown coats

IMG_0053.JPG
Scratch & brown East courtyard

IMG_0078.JPG
Roofing in last section at Southeast penthouse

IMG_7069.JPG
Solar panel supports- no work this week

IMG_7075.JPG
Southeast Penthouse

IMG_7122.JPG
Waterproofing plaza prio to Tuesday's rain

IMG_0125.JPG
Chipping out planter walls for forgotten light fixtures

IMG_7084.JPG
Soil nail wall B second lift ready for shotcrete

IMG_7080.JPG
Existing retaining wall at East side of tech tank



IMG_0138.JPG
Scarifying LSD

IMG_0136.JPG
Paving LSD

IMG_0132.JPG
Boiler room flues 95% connected



IMG_0134.JPG
Boiler room main flue 95% connected



IMG_0131.JPG
Chiller pumps have been running all week during working hours

IMG_0098.JPG
Ductwork installation at cooling tower

IMG_0091.JPG
Ozone- Tech tank support level 2

IMG_0130.JPG
Lockers installed

IMG_0129.JPG
Toilet partition installlation started

IMG_0095.JPG
Ceiling tiles level 2 office area South

IMG_0094.JPG
Wood doors & glass level 2 South

IMG_0093.JPG
Office front glass level 2 South

IMG_0097.JPG
Solid surface window installation strted on levels 2 & 3

IMG_0105.JPG
Level 3 office area Typical North & West

IMG_0106.JPG
Level 3 office Northend of Plaza

IMG_0102.JPG
Level 3 East lab corridor

IMG_0101.JPG
Level 3 East lab typical ceiling grid

IMG_0088.JPG
Driiling holes Nort & South end Tech tank for cover support angle

IMG_0064.JPG
Installing toilet fixtures

IMG_7115.JPG
Cuuting out for low voltage device misplacements

IMG_0076.JPG
Shotcrete level 2 wall B