IMG_1738.JPG
East looking West

IMG_1780.JPG
Plaza South

IMG_1776.JPG
Plaza West



IMG_1777.JPG
Crows Nest

IMG_1742.JPG
East Courtyard

IMG_1790.JPG
West awll sunshades started

IMG_1734.JPG
Roof

IMG_1706.JPG
Planters Southwest corner

IMG_1792.JPG
Entrance

IMG_1789.JPG
Soil nail wall B

IMG_1788.JPG
Soil nail wall C

IMG_1787.JPG
Soil Nail wall D

IMG_1786.JPG
Soil nail wall E

IMG_1737.JPG
Coiling door at emergency generator

IMG_1708.JPG
Tech tank repairs started

IMG_1771.JPG
Level 2 south offices

IMG_1806.JPG
Furniture level 2 Northwest

IMG_1698.JPG
Casework

IMG_1701.JPG
level 4 North office area

IMG_1778.JPG
Level 4 East office area

IMG_1747.JPG
Typical office - level 4 East

IMG_1757.JPG
Casework evel 3 at links

IMG_1760.JPG
Doors at labs level 3

IMG_1779.JPG
Adhesive for sheet vinyl level 4 labs

IMG_1808.JPG
Sealing bottom of wood doors level 3 lab area

IMG_1744.JPG
Preparing for rain - (1/4")

IMG_1799.JPG
Cleaning top of boiler exhaust in Archive room

IMG_1800.JPG
Rework at sea water filters level 1

IMG_1797.JPG
Level 4 Lab casework delivery

IMG_1796.JPG
Furniture delivery level 2 Northwest

IMG_1763.JPG
Lab casework level 3