IMG_1650.JPG
SPWI loading bottom dump truck.
11/9/2009

IMG_1649.JPG
Trucks in queue.
11/9/2009

IMG_1664.JPG
SPWI cleaning up construction entrance and sidewalk.
11/9/2009

IMG_1666.JPG
Street sweeper.
11/9/2009

IMG_1669.JPG
Site looking to the South.
11/10/2009

IMG_1671.JPG
SPWI maintaining the stabilized construction entrance.
11/10/2009

IMG_1675.JPG
SPWI loading an end dump truck.
11/10/2009

IMG_1678.JPG
North County Gunite & Shotcrete mobilizing to grade the earthen "V" ditch.
11/12/2009

IMG_1686.JPG
SPWI loading a bottom dump with two trucks in queue.
11/12/2009

IMG_1687.JPG
North County Gunite & Shotcrete grading the earthen "V" ditch.
11/12/2009

IMG_1689.JPG
North County Gunite & Shotcrete grading the earthen "V" ditch.
11/12/2009

IMG_1692.JPG
Graded earthen "V" ditch.
11/12/2009

IMG_1693.JPG
Graded earthen "V" ditch.
11/12/2009

IMG_1691.JPG
Graded earthen "V" ditch.
11/12/2009

IMG_1703.JPG
SPWI water truck applying water on the haul road for dust control.
11/12/2009

IMG_1718.JPG
Site. Looking to the South.
11/13/2009

IMG_1723.JPG
SPWI loading first truck of the day.
11/13/2009

IMG_1716.JPG
Site. Looking to the North.
11/13/2009