IMG_2204.JPG
Post rain event SWPPP in place.
12/14/2009

IMG_2209.JPG
Clearing and grubbing remaining trees.
12/14/2009

IMG_2224.JPG
Drill Tech lay down area for soil nails.
12/15/2009

IMG_2232.JPG
Drill Tech unloading WWF.
12/15/2009

IMG_2243.JPG
Site looking South.
12/15/2009

IMG_2244.JPG
First load of #10 soil nails.
12/15/2009

IMG_2270.JPG
Drill Tech begins installation of drain strips.
12/16/2009

IMG_2276.JPG
Drill rig moves into drilling position.
12/16/2009

IMG_2292.JPG
2-#10 bars for Verification testing.
12/17/2009

IMG_2296.JPG
SPWI trimming wall face.
12/17/2009

IMG_2300.JPG
Verification bars marked at 10' for bonding length.
12/17/2009

IMG_2304.JPG
Drilling first verification test nail.
12/17/2009

IMG_2312.JPG
6" diameter hole for first verification test.
12/17/2009

IMG_2325.JPG
Hand trimming wall.
12/17/2009

IMG_2353.JPG
Grout placement for Verification Test Nail No. 1.
12/17/2009

IMG_2338.JPG
980 loader loading trucks.
12/17/2009

IMG_2339.JPG
345 excavating and seperation rocks.
12/17/2009

IMG_2363.JPG
Installing WWF for Row 1.
12/17/2009

IMG_2366.JPG
Trucks in queue. Daily load count: 279
12/17/2009

IMG_2367.JPG
Site. Looking West.
12/17/2009

IMG_2369.JPG
Site. Looking east from the construction entrance.
12/18/2009

IMG_2397.JPG
First Shotcrete placement. Row 1 Sta. 5+31 to 3+99
12/18/2009

IMG_2403.JPG
First Shotcrete placement. Row 1 Sta. 5+31 to 3+99
12/18/2009

IMG_2405.JPG
First Shotcrete placement. Row 1 Sta. 5+31 to 3+99. Test panel.
12/18/2009

IMG_2406.JPG
Installing post pockets at top of wall.
12/18/2009

IMG_2411.JPG
First Shotcrete placement. Row 1 Sta. 5+31 to 3+99
12/18/2009

IMG_2413.JPG
Site. Looking West.
12/18/2009

IMG_2414.JPG
Site. Looking West.
12/18/2009

IMG_2418.JPG
Excavation. Looking West. Seperating rocks.
12/18/2009

IMG_2420.JPG
First Shotcrete placement. Row 1 Sta. 5+31 to 3+99
12/18/2009

IMG_2422.JPG
First Shotcrete placement. Row 1 Sta. 5+31 to 3+99
12/18/2009