IMG_2882.JPG
East looking West- Solar panels started

IMG_2906.JPG
Southwest Main Entrance paved

IMG_2909.JPG
View from La Jolla Shores Drive

IMG_2922.JPG
Southwest entrance

IMG_2870.JPG
Paving entrance

IMG_2872.JPG
Shotcrete soil nail wall B- East side

IMG_2785.JPG
Stucco wall repair near stair #2 level 4 - in progress.

IMG_2788.JPG
Setting pavers in bed of adhesive

IMG_2885.JPG
Solar panel installation West wing

IMG_2948.JPG
Green roof at Bridge

IMG_2952.JPG
Flood testing North Plaza

IMG_2965.JPG
Plaza South looking North

IMG_2951.JPG
Plaza- North looking South

IMG_2962.JPG
East courtyard

IMG_2963.JPG
South courtyard

IMG_2966.JPG
Level 4 South planter area

IMG_2969.JPG
Tech Tank roof planter area

IMG_2943.JPG
Level 4 planter area at Director's wing

IMG_2970.JPG
Setting wheel stops garage Level P

IMG_2934.JPG
Garage level 2 used as staging and prep area

IMG_2911.JPG
Main confernce room level 3

IMG_2917.JPG
Library level 2

IMG_2919.JPG
Level 1 main lobby



IMG_2929.JPG
Aquaria setting black out curtain tracks

IMG_2930.JPG
Tuna commission- Level 2 South

IMG_2935.JPG
Status of typical office levels 3 & 4

IMG_2940.JPG
Status of typical ofice area levels 3 & 4

IMG_2936.JPG
Status of typical lab level 3

IMG_2961.JPG
Status of typical lab level 4

IMG_2946.JPG
Director's wing

IMG_2933.JPG
Level 2 South IDC- pulling cat 6A cable

IMG_2956.JPG
VOIP install Rm. 433

IMG_2959.JPG
Rehanging moisture elminators

IMG_2747.JPG
Southeast shaft - tore out wet wall & insulation. Repairs on going